

TECHNICAL BULLETIN GE-31

DATE: NOVEMBER 24, 2004
 MODEL YEAR: 2005
 ENGINE MODEL: J05D-TA
 CHASSIS MODEL: UD1300/UD1400
 BULLETIN NUMBER: GE-31
 FILE IN THE GENERAL SECTION OF THE TECHNICAL BULLETIN BINDER

ENGINE DIAGNOSTIC SWITCH/CONNECTOR LOCATION

SUBJECT

Location of the engine diagnostic switch/connector for the 2005 model year UD1300 and UD1400.


PURPOSE

The 2005 Model Year UD Truck Service Manual CD Page DN02-18 in the Fuel Control (J05D) section incorrectly identifies the location of the engine diagnostic switch/connector.

The correct location for the engine diagnostic switch/connector is on the left side of the dash kick panel as shown below.



I 5	ATM DIAGNOSTIC SWITCH/CONNECTOR
I 6	ENGINE DIAGNOSTIC SWITCH/CONNECTOR
I 7	ABS DIAGNOSTIC SWITCH/CONNECTOR
I 8	PC CONSULT DIAGNOSTIC CONNECTOR



THE INFORMATION CONTAINED IN THIS BULLETIN SHOULD NOT BE INTERPRETED AS THE BASIS FOR WARRANTY CLAIMS

FOR THE INDICATED PERSONNEL BELOW, PLEASE READ, INITIAL, AND ROUTE TO THE FOLLOWING:

X	SERVICE MANAGER	X	WARRANTY MANAGER	X	SERVICE TECHNICIANS INITIAL BELOW:		
X	PARTS MANAGER	X	SHOP FOREMAN				