

TECHNICAL BULLETIN EL-22

DATE: July 25, 2008
 MODEL YEAR: Mid Year Production 2002 ~ Later
 CHASSIS MODEL: Light Duty
 BULLETIN NUMBER: EL-22
 FILE IN THE ELECTRICAL SECTION OF THE TECHNICAL BULLETIN BINDER

A/C DRIER PRESSURE SWITCH HARNESS REPAIR KIT #J49268



PURPOSE

A replacement Air Conditioner Drier Pressure Switch Harness Repair Kit for the four wire drier switch is now available.

GENERAL INFORMATION

The Kit #J49268 includes a four wire plug with 6" lead wires and four heat activated sealing type butt connectors. The kit may be used to replace a damaged or corroded connector without having to replace the entire chassis harness. This kit is now available through the NDA Parts Operations department.

Recommendation: Heat butt connectors with suitable heat gun to melt connector sealer and add die-electric grease to the inside of the connector plug.



THE INFORMATION CONTAINED IN THIS BULLETIN SHOULD NOT BE INTERPRETED AS THE BASIS FOR WARRANTY CLAIMS							
FOR THE INDICATED PERSONNEL BELOW, PLEASE READ, INITIAL, AND ROUTE TO THE FOLLOWING:							
X	SERVICE MANAGER	X	WARRANTY MANAGER	X	SERVICE TECHNICIANS INITIAL BELOW:		
X	PARTS MANAGER	X	SHOP FOREMAN				