

UD Truck Distributors (NZ) Ltd 7 Langley Road, Wiri P O Box 76-326, Manuaku City 2241 Ph: 09 250 1800 Fax: 09 250 1340 www.udtrucks.co.nz

Safety Recall Campaign C0169- Takata Airbag Recall

UD Truck Distributors (NZ) Ltd are recalling UD Quon and Condor vehicles manufactured between August 2011 and April 2016 as part of the global Takata airbag replacement program, where the drivers airbag inflator requires replacement.

Owners of affected vehicles have been advised by letter, we are commencing this recall with oldest vehicles first, your authorised UD Dealer will be in contact to arrange fitment of the replacement driver's airbag.

Due to the large volumes of vehicles impacted globally replacement parts will be released in stages, we expect it could take up to two years to complete this recall.

The replacement is at no cost to the customer