

# TECHNICAL BULLETIN BR-10

DATE: December 18, 2007  
CHASSIS MODEL: 1800CS/HD ~ 3300  
BULLETIN NUMBER: BR-10  
FILE IN THE BRAKE SECTION OF THE TECHNICAL BULLETIN BINDER

## AIR DRYER MAINTENANCE ADVISORY

### PURPOSE



To advise the UD dealer the importance of servicing the air dryer to prevent rust from entering the air system.

### ADVISORY

The air dryer removes the moisture from the compressed air. If the air is not dry, the moisture in the air condenses in the air system and rusts the pipes, brake valve internal parts, fittings and air reservoirs. **See photos below.**

### SERVICE RECOMMENDATION

The air dryer should be serviced with desiccant replacement every year under normal operating conditions or more often in high humidity areas. Refer to the online Service Manuals for complete details.



Air Reservoir Tank



Brake Valve Spring